JX3-THI2-TC

Version Update from V. 1.03 to V. 1.04



Version Update



Version 1.00 September 2013 / Printed in Germany

This Version Update has been compiled by Jetter AG with due diligence, and based on the known state of the art. In the case of modifications, further developments or enhancements to products shipped in the past, a revised Version Update will be supplied only if required by law, or deemed appropriate by Jetter AG. Jetter AG shall neither be liable nor responsible for any errors in form or content, lacks in updating and possibly resulting damages or disadvantages. The logos, band names, and product names mentioned in this Version Update are trade marks of Jetter AG, of associated companies or other title owners and must not be used without consent oif the respective title owner.

Table of Contents

1	Introduction	4
	Operating system update	5
	JX3-THI2-TC version update - Overview	
2	Fixed software bugs	7
	Querying the oscilloscope within JetSym is terminated and an error message is issued	8
	The reference of the trailing indicator has been corrected	

Introduction 1

Introduction

This chapter shows the history of OS versions.

Operating system update - why?

An operating system offers you the following opportunities:

- Adding new functions to your device
- Fixing software bugs
- Transmitting an OS of a certain state, e. g. a new OS release

Contents

Topic	Page
Operating system update	5
JX3-THI2-TC version update - Overview	6

Operating system update

OS file for an operating system update

For an OS update, you will need the following file:

OS file	Description
JX3-THI2-TC_1.04.0.00.os	OS file for JX3-THI2-TC with version 1.04.0.00.

Downloading the OS file

Jetter AG provides OS files for operating system download on our **homepage http://www.jetter.de**. OS files can be found in the support area. Another option is to follow the quick link on the JX3-THI2-TC page.

OS update by means of JetSym

To update the OS, proceed as follows:

Step	Action	
1	Download the OS file from www.jetter.de.	
2	Establish a connection between PC and controller.	
3	Execute the menu item Build > Operating System Update in JetSym.	
4	Select the OS file.	
5	Depending on the controller and on the module, the following items have to be specified:	
	 Module number Submodule position Slave number I/O module number 	
6	Start the operating system update by clicking OK.	
7	Result: Following Power OFF/Power ON the new OS is launched.	

JX3-THI2-TC version update - Overview

V. 1.03

The following table gives an overview of newly added features and fixed software bugs in OS version 1.03:

Function	New	Fixed
JX3-THI2-TC:		
Due to incorrect evaluation of thermocouple type J the diagnostic LED D2 is permanently lit.		✓

V. 1.04

The following table gives an overview of newly added features and fixed software bugs in OS version 1.04:

Function	New	Fixed
JX3-THI2-TC:		
Oscilloscope mode has been corrected.		✓
Trailing indicator has been corrected from "measured voltage" to "process data value".		✓

2 Fixed software bugs

Introduction	This chapter describes the software bugs which have been fixed OS version.	This chapter describes the software bugs which have been fixed in the new OS version.	
Contents			
	Topic	Page	
	Querying the oscilloscope within JetSym is terminated and an error me issued.		
	The reference of the trailing indicator has been corrected	9	

Querying the oscilloscope within JetSym is terminated and an error message is issued.

Symptoms

If you set the oscilloscope mode **Compatible Mode** in JetSym and start querying by **Start**, there will be the message **Ready** shortly afterwards. Yet, the oscilloscope won't show any data.

If recording functions correctly, in the window next to the **Start** and **Stop** buttons, these messages appear in the following sequence:

- Recording
- Loading channel xxx
- Ready

Affected versions/revisions

The following versions/revisions of JX3-THI2-TC are affected by this bug:

Operating system version	< 1.04.0.00
Hardware revision	Not relevant
Configuration or operating mode	Not relevant

Remedy/workaround

There is no remedy to be applied to the releases concerned.

Fixed versions/revisions

Starting from the following version/revision of the JX3-THI2-TC, this bug has been fixed:

Operating system version	1.04.0.00
Hardware revision	Not relevant
Configuration or operating mode	Not relevant

The reference of the trailing indicator has been corrected

Symptoms The trailing indicator always refers to the measured voltage, not to the

measured temperature.

Affected versions/revisions

The following versions/revisions of JX3-THI2-TC are affected by this bug:

Operating system version	< 1.04.0.00
Hardware revision	Not relevant
Configuration or operating mode	Not relevant

Remedy/workaround There is no remedy to be applied to the releases concerned.

Fixed versions/revisions Starting from the following version/revision of the JX3-THI2-TC, this bug has been fixed:

Operating system version	1.04.0.00
Hardware revision	Not relevant
Configuration or operating mode	Not relevant